# MAHARSHI DAYANAND UNIVERSITY, ROHTAK NOTICE INVITING QUOTATIONS

Sealed percentage/item rate quotation are hereby invited by the undersigned for and on behalf of Registrar, M.DUniversity, Rohtak for the below noted work from the suppliers/Agencies/Contractors/societies registered with Haryana P.W.D.B & R. M.E.S & Central P.W.D. Or any other State/ Central. Gov. Department on date. 16 /05/2024 at 03:00 PM for societies and on dated 17/05/2024 at 03:00 PM the both contractors &societies quotations will be opened at the same date and time in the presence of quotation or representative who may like to be present at that time. However, preference will be given to societies first, if two or more societies participated and found eligible. DINQ may be seen on University website or in the office of Sub-Division.

Description	App. Amount	Time limit	
Repair of Sofa by removing old cloth foam, spring, fiber and replacing new spring, Room in Guest House in MDU Rohtak.	Rs. 48,000/-	10 Days	
Distempering painting in Type-I/119,111, 89&73 in MDU Rohtak.	RS.47,500/-	10 Days	
Distempering painting in Type- III/11 water tank for type 1A/129 flat and name Plate For camp office in MDU Rohtak	RS.30,000/-	10 Days	
Repairing work in House No 79/Type-II, H.N14/ Type-III, H.N 20/ Type-II in MDU Rohtak	RS.24,000/-	10 Days	
OBD, Putty, Paint Work in HN 101/Type-IA flat, HNo-17/Type-III & Warden's Residence in MDU Rohtak.	RS.41,000/-	10 Days	
	Repair of Sofa by removing old cloth foam, spring, fiber and replacing new spring, Room in Guest House in MDU Rohtak.  Distempering painting in Type-I/119,111, 89&73 in MDU Rohtak.  Distempering painting in Type-III/11 water tank for type 1A/129 flat and name Plate For camp office in MDU Rohtak.  Repairing work in House No 79/Type-II, H.N14/ Type-III, H.N 20/ Type-II in MDU Rohtak  OBD, Putty, Paint Work in HN 101/Type-IA flat HNo-	Repair of Sofa by removing old cloth foam, spring, fiber and replacing new spring, Room in Guest House in MDU Rohtak.  Distempering painting in Type-I/119,111, 89&73 in MDU Rohtak.  Distempering painting in Type-III/11 water tank for type 1A/129 flat and name Plate For camp office in MDU Rohtak.  Repairing work in House No 79/Type-II, H.N14/ Type-III, H.N 20/ Type-II in MDU Rohtak  OBD, Putty, Paint Work in HN 101/Type-IA flat HNo-	

#### Conditions:-

1. The work will be carried out strictly in accordance with the PWD Haryana Specification and approved DINQ.

2. Other taxes will be deducted as applicable from time to time.

Sub –Divisional Engineer (C-I) M.D. University, Rohtak.

SDE/(C-I)/2024/ 190—194	7/01/24
Cope of the above is forwarded to the following inform	nation and necessary action:-

- 1. The Executive Engineer/C-I, M.D. University, Rohtak.
- 2. The Executive Engineer /C-II M.D. University, Rohtak.

3. Notice Board

4. Directed, UCC for Uploading it on University web site

5. Contractors / Agencies.

Sub -Divisional Engineer (C-I)

M.D. University, Rohtak

Name of the work- Repair of Sofa by removing old cloth foam , spring, fiber and replacing new spring, Room in Guest House in MDU University,

App. Amount RS-

Time Limit: 10 Days

S.No	H.S.R/ Ref.No	Description	Qty.	Unit	Rate to be quoted by the bidder exclusive of GST, but including all other taxes, if any
1.	NS	Repair of Sofa by removing old cloth foam, spring, fiber and replacing new spring, foam, fiber and new cloth complete with polish	6 seat	Sqm	

Name of the work- Distempering painting in Type-I/119,111, 89&73 in MDU University,

App. Amount RS-

Time Limit: 10 Days

S.No	H.S.R/ Ref.No	Description	Qty.	Unit	Rate to be quoted by the bidder exclusive of GST, but including all other taxes, if any
1.	30.34.1	Distempering with OBD	979.76	Sqm	
2.	30.28.1	Painting one Coat	409.24	Sqm	
3.	30.22	Scrapping OBD	84.28	Sqm	
4.	11.58	Apply wall putty	84.28	Sqm	

Name of the work- Distempering painting in Type- III/11 water tank for type 1A/129 flat and name Plate For camp office. in MDU University,

App. Amount RS-

Time Limit: 10 Days

S.No	H.S.R/ Ref.No	Description	Qty.	Unit	Rate to be quoted by the bidder exclusive of GST, but including all other taxes, if any
			y.		5
1.	30.34.1	Distempering with OBD	343.99	Sqm	
2.	30.28.1	Painting with paint	146.00	Sqm	
3.	30.22	Scrapping/Removing OBD	39.84	sqm	
4.	11.58	Apply wall putty	19.99	Sqm	
5.	22.181	P/ fixing PVC Water tank	1000	Ltr	
6.	N.S	Making Acryline Name plate	13.57	Sqm	

Name of the work- Repairing work in House No 79/Type-II, H.N14/ Type-III, H.N 20/ Type-II in MDU Rohtak

App. Amount RS-

Time Limit: 10 Days

S.No	H.S.R/ Ref.No	Description	Qty.	Unit	Rate to be quoted by the bidder exclusive of GST, but including all other taxes, if any
1.	30.34.1	Distempering with 1st quality acrylic distemper	311.99	Sqm	
2.	30.22	Removing OBD	47.75	Sqm	
3.	11.58	Providing cement based putty	47.75	sqm	
4.	30.28.1	Painting with synthetic enamel paint	131.14	Sqm	
5.	22.182	Providing and fixing rectangular high density Water tank	500	Ltr	
6.	12.36.2	Flush door shutter 30mm	1.380	Sqm	

Name of the work:- OBD, Putty, Paint Work in HN 101/Type-IA flat, HNo-17/Type-III & Warden's Residence in MDU Rohtak

App. Amount RS-

Time Limit: 10 Days

S.No	H.S.R/ Ref.No	Description	Qty.	Unit	Rate to be quoted by the bidder exclusive of GST, but including all other taxes, if any
1.	30.34.1	OBD one coat	381.982	Sqm	
2.	30.22	Scrapping/Removing OBD	58.682	Sqm	
3.	11.58	Providing cement based putty	79.202	Sqm	
4.	30.28.1	Painting with synthetic enamel paint	100.380	Sqm	
5.	19.33	Providing and fixing percolated galvanised iron	20	Sqm	
6.	5.7.4	Demolishing brick work manually In cement mortar	0.554	Cum	
7.	7.22.1	Brick work with common burnt clay	0.554	Cum	
8.	12.36.1	Providing and fixing ISi marked flush door shutter	1.60	Sqm	_
9.	12.10.2.2	Providing and fixing glazed shutters for doors with 4mm glass	0.770	Sqm	
10.	12.19.2.1.2	Providing and fixing wire gauge shutters for window	0.770	Sqm	
11.	N.S	Removing shutter	1	nos	