Vec 1036

# MAHARSHI DAYANAND UNIVERSITY, ROHTAK NOTICE INVITING QUOTATIONS

Sealed percentage/item rate quotation are hereby invited by the undersigned for and on behalf of noted University, Rohtak for the below work Registrar. M.D suppliers/Agencies/Contractors/societies registered with Haryana P.W.D.B & R.M.E.S & Central P.W.D. Or any other State/ Central. Govt. Department on date 19/05/2025 at 03:00 PM for societies and on dated 20/05/2025 at 03:00 PM the both contractors & societies quotations will be opened at the same date and time in the presence of quotationers or representative who may like to be present at that time. However, preference will be given to societies first, if two or more societies participated and found eligible. DINO may be seen on University website or in the office of Sub-Division.

Sr. No.	<u>Description</u>	App. Amount	Time limit
1.	Distempering, painting and P/F floor tiles in skirting at F/F in 9J/15 in MDU, Rohtak	Rs.32100	07 Days
2.	Distempering, painting & replacement of damaged door frame and shutters in Type-II/75 in MDU, Rohtak	Rs.49100	07 Days
3.	Repair of broken flooring in front court yard in 9J/2 in MDU, Rohtak	Rs.37400	07 Days
4.	Repair and construction of CC floor in back & front court yard in Type-IIA/4 in MDU, Rohtak	Rs.34330	07 Days
5.	Repair of RCC seating benches and P/F granite stone and wall tile in park Type-1/A & Repair of roof with polymer modified mortor in Type/48' in MDU, Rohtak	Rs.38100	07 Days

#### Conditions:-

- 1. The work will be carried out strictly in accordance with the PWD Haryana Specification and approved DINQ.
- 2. Other taxes will be deducted as applicable from time to time.

Sub –Divisional Engineer (C-I) M.D. University, Rohtak.

-.54

DDDDDDDDDDDDDDDDDDDDDDDDDDDDDDDDDDDDDD	SDE/(C-D/2025/	150-158	Dated 1915/95
--	----------------	---------	---------------

Cope of the above is forwarded to the following information and necessary action:-

- 1. The Executive Engineer/C-I, M.D. University, Rohtak.
- 2. The Executive Engineer/C-II, M.D. University, Rohtak.
- 3. Notice Board
- 4. Directed, UCC for Uploading it on University web site
  - 5. Contractors / Agencies.

Sub – Divisional Engineer (C-I)

M.D. University, Rohtak

00

Name of the work: - Distempering, painting and P/F floor tiles in skirting at F/F in 9J/15 in MDU, Rohtak

Time Limit: 07 Days

Sr. No.	H.S.R/ Ref.No	Description	Qty.	Unit	Rate to be quoted by the bidder exclusive of GST, but including all other taxes, if any
1.	30.34.1	Distemper with OBD	579.38	Sqm	
2.	30.28.1	Painting with paint	129.22	Sqm	-
3.	10.63.2+10.65- 10.64	P/L vitrified tile in floor	5.10	Spm	
4.	10.67.2	P/F vitrified tiles 600*600mm in skirting	4.94	Sqm	



Name of the work: - Distempering, painting & replacement of damaged door frame and shutters in Type-II/75 in MDU, Rohtak

Time Limit: 07 Days

Sr. No.	H.S.R/ Ref.No	Description	Qty.	Unit	Rate to be quoted by the bidder exclusive of GST, but including all other taxes, if any
1.	30.24.1	Distempering with OBD	311.99	Sqm	
2.	30.22	Removing of OBD	23.87	Sqm	
3.	11.58	P/A wall Putty	23.87	Sqm	
4.	.30.28.1	P/A with paint	131.14	Sqm	
5.	12.37.2	P/F solide flush door 30mm thick	1.24	Sqm	
6.	N.S.	P/F pressed steel chowkhet	10.36	Mtr.	
7.	22.209	P/F 60mm*450mm bevelled edge mirror	01	nos	
8.	10.58	P/F cermic wall tile as per Req. Size	13.37	Sqm	
9.	5.45	Dismantling old plaster	13.37	Sqm	-
10.	31.2	Chipping of weak concrete	40.87	Sqm	
11.	31.4.1	P/M/A boundary coat of adhesive	40.87	Sqm	
12.	31.7.2	P/M/A polymer modified mortor 1:4	40.87	Sqm	



Name of the work: - Repair of broken flooring in front court yard in 9J/2 in MDU, Rohtak

Time Limit: 07 Days

Sr. No.	H.S.R/ Ref.No	Description	Qty.	Unit	Rate to be quoted by the bidder exclusive of GST, but including all other taxes, if any
1.	31.2	Chipping of weak concrete	91.15	Sqm	
2.	31.4.1	Applying SBR polymer boundary coat	91.15	Sqm	
3.	31.7.2	Applying SMB modified mortor 1:4	91.15	Sqm	



Name of the work: - Repair and construction of CC floor in back & front court yard in Type-IIA/4 in MDU, Rohtak

Time Limit: 07 Days

Sr. No.	H.S.R/ Ref.No	Description	Qty.	Unit	Rate to be quoted by the bidder exclusive of GST, but including all other taxes, if any
1.	10.100.1	Cement concrete 1:8:16 with 40mm b/ballast	4.84	Cum	
2.	10.8	40mm th. Topping C.floor1:2:4	113.19	Sqm	



Name of the work: - Repair of RCC seating benches and P/F granite stone and wall tile in park Type-1/A & Repair of roof with polymer modified mortor in Type/48, in MDU, Rohtak

Time Limit: 07 Days

Sr. No.	H.S.R/ Ref.No	Description	Qty.	Unit	Rate to be quoted by the bidder exclusive of GST, but including all other taxes, if any
1.	30.16.1	Applying plaster 12 to 20 mm	4.27	Sqm	
2.	10.50	P/L Polished granite stone	11.81	Sqm	
3.	10.58	P/F wall tile as per Req. Size	10.03	Sqm	
4.	31.2	Chipping of weak concrete	11.47	Sqm	
5.	31.4.1	P/Mixing SBR polymer boundary coat	11.47	Sqm	
6.	34.7.2	P/Mixing SBR polymer modified mixture	11.47	Sqm	
7.	30.94	P/F Scaf Holding	9.66	Sqm	"

